

DRIVE.

VW325R DRIVESHAFT INSTALLATION ADVICE




VW325R Driveshaft

These Driveshafts are designed to OE specifications and premature failure may occur on applications with modified suspension and or ride heights

The inner joint of the driveshaft has a working range of up to 16°, under normal operation this will not be exceeded.

However, if the joint is unsupported on fitment and exceeds 22° there is a risk of the inner joint becoming dislocated, it is recommended that on handling that the driveshaft is supported sufficiently to ensure the inner CV joint does not exceed 22°.



NB: This may apply to other applications of a similar design.

STEC.10037 10/11/2022

